

One exception is the old connection that was previously used for a Y/YY motor (230/460-60Hz). Its new DR equivalent is **R76**, not R79.

With only 6 terminal posts, the R76 requires a totally different wiring diagram as shown below.

